Maryland Historical Trust

Maryland Inventory of Historic Properties number:	697
Name: BO400/ Sungowder Rl ov	Tub of Georges 1
\mathcal{V}	0
The bridge referenced herein was inventoried by the Maryland Sta Historic Bridge Inventory, and SHA provided the Trust with eligib The Trust accepted the Historic Bridge Inventory on April 3, 2001 determination of eligibility.	pility determinations in February 2001
MARYLAND HISTORICAL Eligibility Recommended	TRUST
Eligibility Recommended	Eligibility Not RecommendedX
MARYLAND HISTORICAL Eligibility Recommended F Criteria:ABCD Considerations:A Comments:	Eligibility Not RecommendedX
Eligibility Recommended F Criteria:ABCD Considerations:A Comments:	Eligibility Not RecommendedX
Eligibility Recommended E Criteria:ABCD Considerations:A	Eligibility Not RecommendedX

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

MHT No. <u>BA-2697</u>

SHA Bridge No. B 0400 Bridge name Gunpowder Road over Tributary of Georges
LOCATION: Street/Road name and number [facility carried] Gunpowder Road
City/town Armacost 0.66 mi N of MD 25 Vicinity X
County Baltimore
This bridge projects over: Road Railway Water X Land
Ownership: State County X Municipal Other
HISTORIC STATUS: Is bridge located within a designated historic district? Yes NoX National Register-listed district National Register-determined-eligible district Locally-designated district Other Name of district
BRIDGE TYPE: Timber Bridge: Beam Bridge: Truss -Covered Trestle Timber-And-Concrete Stone Arch Bridge Metal Truss Bridge
Movable Bridge: Swing: Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder: Rolled Girder: Rolled Girder: Plate Girder Concrete Encased
Metal Suspension
Metal Arch
Metal Cantilever
Concrete X: Concrete Arch Concrete Slab X Concrete Beam Rigid Frame Other Type Name

DESCRIPTION:	
Setting: Urban_	Small town Rural X
Describe Setting:	Bridge B0400 carries Gunpowder Road in a east-west direction over a tributary
of Georges Run w	hich flows in a southerly direction. The area is relatively undeveloped with a horse
farm near the bri	dge and with open fields and scattered wooded areas around it.
Describe Superst	ructure And Substructure:
Bridge B0400 is a	single span concrete slab bridge on concrete abutments and concrete wingwalls.
The bridge was	built in 1920, and reconstructed in 1984. The curb to curb width is 190 feet and
the deck out to c	out width is 19.7 feet. The clear span is 17.8 feet, and the overall length of the
structure is 20.5 i	eet. The skew is 15 degrees. The wingwalls are flared at varying angles to the
removed and real	bridge from approximately 15 degrees to 70 degrees. The parapets have been
posted. The 1003	aced with steel guardrail. The roadway supports two way traffic. The bridge is not
and spalling.	inspection report describes the bridge as in good condition, with minor cracking
ana spaning.	
Discuss Major Al	terations:
	ete slab and parapets were removed.
HISTORY:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
WHEN was bridg	e built (actual date or date range) 1920, reconstructed 1984
This date is: Act	ual X Estimated
Source of date: Pl	laque Design plans County bridge files/inspection form X
Other (specify)	
WHY was the brid	dao built?
	ore efficient transportation network and increased load capacity in the decades
following World V	War I
8	
WHO was the des	
State Highway Ac	ministration

WHO was the bui	lder?
Unknown	
WHY was the brid	dga altorod?
	tered to accommodate increased weights, widths, and numbers of vehicles, plus
structural deficien	cies.
WAS this bridge l	ouilt as part of an organized bridge-building campaign?
As part of an effo	rt by the State to increase load capacity on secondary roads during the 1920s.
SURVEYOR/HIST	CORIAN ANALYSIS:
This bridge may b	nave National Register significance for its association with:
A - Events	B- Person
	ering/architectural character
This bridge does r	not have National Register significance.

Was the bridge constructed in response to significant events in Maryland or local history? Yes, original bridge. Reinforced concrete slab bridges are a twentieth century structure type, easily adapted to the need for expedient engineering solutions. Reinforced concrete technology developed rapidly in the early twentieth century with early recognition of the potential for standardized design. The first U.S. attempt to standardize concrete design specifications came in 1903-04 with the formation of the Joint Committee on Concrete and Reinforced Concrete of the American Society of Civil Engineers.

Maryland's road and bridge improvement programs mirrored economic cycles. The first road improvement program of the State Roads Commission was a 7 year program, starting with the Commission's establishment in 1908 and ending in 1915. Due to World War I, the period from 1916 -1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war-related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920 to 1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund [with an equal sum from the counties] the building of lateral roads. The number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930. By 1930, Maryland's primary system had become inadequateto the huge freight trucks and volume of passenger cars in use, with major improvements occurring in the late 1930s. Most improvements to local roads waited until the years after World War II.

With a diverse topographical domain encompassing numerous small and large crossings, Maryland engineers quickly recognized the need for expedient design and construction.

In the early years, there was a need to replace the numerous single lane timber bridges. Walter Wilson Crosby, Chief Engineer stated in 1906, "The general plan has been to replace these [wood bridges] with pipe culverts or concrete bridges and thus forever do way with the further expense of the maintenance of expensive and dangerous wooden structures". Within a few years, readily constructed standardized bridges of concrete were being built throughout the state.

The creation of standard plans and a description of their use was first announced in the 1912-15 Reports of the State Roads Commission whereby bridges spanning up to 36 feet were to use standardized designs.

Published on a single sheet, the 1912 Standard Plans included those structures that were amenable to such an approach: slab spans, (deck) girder spans, box culverts, box bridges, abutments, and piers (State Roads Commission 1912). Slab spans, with lengths of 6 to 16 feet in two foot increments, featured a solid parapet that was integrated into the slab, with a roadway of 22 feet.

In the Report for the years 1916-1919, a revision of the standard plans was noted:

During the four years covered by this report, it has been found necessary to revise our standard plans for culverts and bridges, to take care of the increased tonnage which they have been forced to carry. Army cantonments...increased their operations several hundred

per cent, and the brunt of the enormous truck traffic resulting therefrom, was borne by the State Roads of Maryland. In addition to these war activities, freight motor lines from Baltimore to Washington, Philadelphia, New York, and various points throughout Maryland, and the weight of many of these trucks when loaded, was in excess of the loads for which our early bridges were designed (State Roads Commission 1920:56).

Published on separate sheets, the new standard plans (State Roads Commission 1919) for slab bridges reveal that the major changes was an increase in roadway width from 22 feet to 24 feet and a redesign of the reinforcement. The slab spans continued to feature solid parapets integrated into the span. The range of span lengths remained 6 to 16 feet, but the next year (1920) witnessed the issue of a supplemental plan for a 20 foot long slab span (State Roads Commission 1920).

Based upon documentary evidence, Baltimore County and City were the early pioneers in concrete bridge building in Maryland. The first reinforced concrete bridge documented in Maryland was the bridge at Sherwood Station, built in 1903 by Baltimore County.

Evidence from historic maps suggests that almost all of the extant concrete slab bridges built before 1940 in Baltimore County replaced earlier bridges. With the exception of two bridges, all of these structures lie on roads whose alignments have changed little since the middle of the nineteenth century. The two exceptions are both located on Shelbourne Avenue in Arbutus. Shelbourne Avenue does not appear on the 1850 map of Baltimore County but does appear on the 1915 map. Both concrete slabs bridges on Shelbourne Avenue, however, were built after 1915. The evidence therefore suggests that these two bridges were also built to replace previous structures.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence to suggest that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation? Would the bridge add to or detract from the historic/visual character of the potential district? The bridge is not located in an area which may be eligible for historic designation.

Is the bridge a significant example of its type?

No, this bridge is not a significant example of its type.

Does the bridge retain integrity of important elements described in Context Addendum? No, this bridge was reconstructed in 1984 when the slabs and parapets were replaced.


Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer? The bridge is not a significant example of the work a manufacturer, designer, and/or engineer.

Should the bridge be given further study before an evaluation of its significance is made? No additional study will be needed before an evaluation of the significance of this bridge is made.

BIBLIOGRAPHY:			
County inspection/bridge files _ Other (list):	X	SHA inspection/bridge files	

SURVEYOR:

Date bridge recorded	08/15/95	
Name of surveyor	Colin Farr	
Organization/Address	P.A.C. Spero & Compar	y, Suite 412, 40 West Chesapeake Ave., Baltimore,
MD 21204	-	
Phone number (410) 2	96-1635	FAX number (410) 296-1670





Inventory # <u>BA 2697</u>
13 0400 - GUNDOWOER RD OVER A BRANCH Name OF GEORGES RUN
County/State BALTIMORE COUNTY/MD
Name of Photographer DAVE DIEHL
Date 1/95
Location of Negative SHA
Description SOUTH APPROACH WOKING NORTH EAST
NORTH EAST
1 4
Number 8 of 224



Inventory # <u>8A 269</u> 7
BOHOD-GUNPOWDER ROOVER A BRANCHOO Name GEORGES RUN
County/State BALTIMORE COUNTY MO
Name of Photographer DAVE DIEHL
Date 1 05
Location of Negative 5HA
Description WEST ELEVATION LOOKING
sound
A DOMESTIC TO THE PROPERTY OF THE PARTY OF T
1 4
Number 9 of 28



Inventory #	BA 2691	7	
30400 - 6 Name OF	GEOR	ER RD OVER A	BRANCH
		YORE COUNTY	
Name of Pho	tographer	DAVE DIEN	_
Date	95		
Location of	Negative _	SHA	
Description		ELEVATION	MOKING
	WEST		
4			
. 310	.204		
Number 10	Of		



Inventory # <u>BA 2697</u>
BOYOU-GUNPOWDER RD OVER A BRANCH OF
Name GEORGES RUN
County/State BALTIMORE COUNTY/MO
Name of Photographer DAVE DEHL
Date 195
Location of Negative SHA
Description NORTH APPROACH LOOKING
SOUTHWEST
Number H of 224